


# WIRING DIAGRAM

BLK:BLACK    YEL:YELLOW  
 BLU:BLUE    GRN:GREEN  
 RED:RED    WHT:WHITE  
 GRY:GRAY    BRN:BROWN



<p><b>CAUTION!</b> HIGH VOLTAGE</p>	<p>TURN OFF THE POWER SOURCE DURING THE SERVICE WORK.</p>
---	---

\*SOME CONNECTOR MAY NOT BE INSTALLED.  
PLEASE ACCORDING TO THE SPECIFIC OF  
ACTUAL MODELS